

AAA PIPELINE INSPECTION
6308 KENNETH AVE.
ORANGEVALE, CA. 95662
916-988-7198

LOG REPORT
04-07-99

CITY:MOUTAIN VIEW
DATE:04-07-99
OPERATOR:JOSE MONTOYA
TAPE#20
TAPE START:1675
MAP PAGE:G-6
SET UP#:MVT20-7

PIPE INFORMATION
UPSTREAM MH#38
DOWNSTREAM MH#26
PIPE TYPE:VCP
PIPE SIZE:12"
STREET:WHISMAN RD.
TV WITH THE FLOW

THANK YOU FOR CHOOSING
AAA PIPELINE INSPECTION

cracks 120x3
sags 130x3
131x4
Joints offset 150x6

FOOTAGE:	FAULT OR COMMENTS:
4.0 Ft	CRACKED PIPE 120
56.2 Ft	START SAG IN LINE 130
61.4 Ft	SAG IN LINE (CAMERA UNDER WATER)
72.7 Ft	OUT OF SAG IN LINE
111.7 Ft	OFFSET JOINT 150
115.2 Ft	LATERAL LEFT @ 10 O'CLOCK
145.6 Ft	START SAG IN LINE
149.3 Ft	SAG IN LINE (CAMERA UNDER WATER) 131
156.7 Ft	SAG IN LINE (CAMERA UNDER WATER)
159.8 Ft	OUT OF SAG IN LINE
186.1 Ft	OFFSET JOINT 150
189.9 Ft	OFFSET JOINT 150
193.8 Ft	OFFSET JOINT 150
202.6 Ft	OFFSET JOINT 150
215.1 Ft	OFFSET JOINT 150

223.4 Ft	CRACKED PIPE 120
233.9 Ft	LATERAL LEFT @ 10 O'CLOCK
234.2 Ft	START SAG IN LINE
237.4 Ft	SAG IN LINE (CAMERA UNDER WATER)
242.8 Ft	SAG IN LINE (CAMERA UNDER WATER) 131
251.7 Ft	SAG IN LINE (CAMERA UNDER WATER)
258.3 Ft	OUT OF SAG IN LINE
260.1 Ft	LATERAL RIGHT @ 2 O'CLOCK
265.7 Ft	START SAG IN LINE
267.1 Ft	SAG IN LINE (CAMERA UNDER WATER) 130
279.8 Ft	SAG IN LINE (CAMERA UNDER WATER) 130
283.3 Ft	OUT OF SAG IN LINE
301.8 Ft	START SAG IN LINE 131
304.7 Ft	SAG IN LINE (CAMERA UNDER WATER)
311.6 Ft	CRACKED PIPE 120
316.1 Ft	SAG IN LINE (CAMERA UNDER WATER) 131
319.6 Ft	END OF LINE LINE POOR

FAIR

AAA PIPELINE INSPECTION
6308 KENNETH AVE.
ORANGEVALE, CA. 95662
916-988-7198

(C)

LOG REPORT
04-07-99

CITY:MOUNTAIN VIEW
DATE:04-07-99
OPERATOR:JOSE MONTOYA
TAPE#20
TAPE START:1930
MAP PAGE:G-6
SET UP#:MVT20-8

PIPE INFORMATION
UPSTREAM MH#26
DOWNSTREAM MH#24
PIPE TYPE:VCP
PIPE SIZE:12"
STREET:WHISMAN RD.
TV WITH THE FLOW

cracks 120x3
sags 130x5
offset joints 150x17
infiltration 180x11

THANK YOU FOR CHOOSING
AAA PIPELINE INSPECTION

FOOTAGE:	FAULT OR COMMENTS:
3.0 Ft	INFILTRATION INTO PIPE 180 CRACKED PIPE 120
16.2 Ft	SAG IN LINE (CAMERA UNDER WATER) 130
27.5 Ft	INFILTRATION INTO PIPE 180
31.4 Ft	INFILTRATION INTO PIPE 180
35.2 Ft	OFFSET JOINT 150
39.1 Ft	OFFSET JOINT 150
42.9 Ft	OFFSET JOINT 150 CRACKED PIPE 120
44.1 Ft	OFFSET JOINT 150
50.6 Ft	OFFSET JOINT 150
58.4 Ft	INFILTRATION INTO PIPE 180
62.3 Ft	CRACKED PIPE 120 INFILTRATION INTO PIPE 180
69.9 Ft	INFILTRATION INTO PIPE 180
73.6 Ft	INFILTRATION INTO PIPE 180
77.4 Ft	OFFSET JOINT 150

81.8 Ft	INFILTRATION INTO PIPE 180
86.2 Ft	OFFSET JOINT 150
92.5 Ft	INFILTRATION INTO PIPE 180
93.7 Ft	OFFSET JOINT 160
106.2 Ft	OFFSET JOINT 150
110.3 Ft	OFFSET JOINT 160
115.0 Ft	OFFSET JOINT 150
116.2 Ft	START SAG IN LINE 130
119.2 Ft	OFFSET JOINT 150
122.7 Ft	SAG IN LINE (CAMERA UNDER WATER) 130
137.6 Ft	OUT OF SAG IN LINE
139.5 Ft	OFFSET JOINT 150
148.8 Ft	LATERAL AT TOP
163.7 Ft	OFFSET JOINT 150
165.2 Ft	START SAG IN LINE 130
179.9 Ft	OFFSET JOINT 150
185.1 Ft	SAG IN LINE (CAMERA UNDER WATER) 130
205.3 Ft	INFILTRATION INTO PIPE 180
211.3 Ft	INFILTRATION INTO PIPE 180
216.7 Ft	OUT OF SAG IN LINE
221.2 Ft	OFFSET JOINT 150
234.0 Ft	OFFSET JOINT 150
257.4 Ft	START SAG IN LINE 130
268.8 Ft	END OF LINE
268.8 Ft	LINE POOR

FAIR

AAA PIPELINE INSPECTION
6308 KENNETH AVE.
ORANGEVALE, CA. 95662
916-988-7198

(C)

LOG REPORT
04-07-99

CITY:MOUTAIN VIEW
DATE:04-07-99
OPERATOR:JOSE MONTOYA
TAPE#20
TAPE START:2175
MAP PAGE:G-6
SET UP#:MVT20-9

PIPE INFORMATION
UPSTREAM MH#24
DOWNSTREAM MH#6
PIPE TYPE:VCP
PIPE SIZE:12"
STREET:WHISMAN RD.
TV WITH THE FLOW

THANK YOU FOR CHOOSING
AAA PIPELINE INSPECTION

Cracks 120 x 2
Sags 130 x 1
Offset joints 150 x 22
Infiltration 120 x 5

FOOTAGE:

FAULT OR COMMENTS:

19.9 Ft

OFFSET JOINT 150

45.5 Ft

OFFSET JOINT 150

53.5 Ft

OFFSET JOINT 150

62.5 Ft

INFILTRATION INTO PIPE 180

65.5 Ft

OFFSET JOINT 150

69.9 Ft

CRACKED PIPE 120

74.3 Ft

INFILTRATION INTO PIPE 180

80.2 Ft

INFILTRATION INTO PIPE 180

89.9 Ft

OFFSET JOINT 150

96.2 Ft

INFILTRATION INTO PIPE 180

98.6 Ft

OFFSET JOINT 150

119.0 Ft

LATERAL AT TOP

147.7 Ft

OFFSET JOINT 150

172.5 Ft

OFFSET JOINT 150

176.2 Ft

OFFSET JOINT 150

181.1 Ft

OFFSET JOINT 150

185.4 Ft	OFFSET JOINT 150
205.0 Ft	OFFSET JOINT 150
217.9 Ft	OFFSET JOINT 150
230.2 Ft	OFFSET JOINT 150
233.8 Ft	OFFSET JOINT 150
240.1 Ft	LATERAL RIGHT @ 2 O'CLOCK
240.2 Ft	INFILTRATION INTO PIPE 180
251.2 Ft	OFFSET JOINT 150
255.0 Ft	OFFSET JOINT 150
256.3 Ft	START SAG IN LINE 130
258.7 Ft	OFFSET JOINT 150
262.9 Ft	OFFSET JOINT 150
267.4 Ft	OFFSET JOINT 150
269.5 Ft	OUT OF SAG IN LINE
279.8 Ft	OFFSET JOINT 150
283.5 Ft	OFFSET JOINT 150
294.1 Ft	CRACKED PIPE 180
297.7 Ft	END OF LINE LINE POOR Fair

AAA PIPELINE INSPECTION
6308 KENNETH AVE.
ORANGEVALE, CA. 95662
916-988-7198

LOG REPORT
04-07-99

CITY: MOUNTAIN VIEW
DATE: 04-07-99
OPERATOR: JOSE MONTOYA
TAPE#20
TAPE START: 2349
MAP PAGE: G-6
SET UP#: MVT20-10

PIPE INFORMATION
UPSTREAM MH#6
DOWNSTREAM MH#69
PIPE TYPE: VCP
PIPE SIZE: 12"
STREET: WHISMAN RD.
TV WITH THE FLOW

THANK YOU FOR CHOOSING
AAA PIPELINE INSPECTION

cracks 120x4
sags 130x3
offset joints 150x44
(C)

FOOTAGE:	FAULT OR COMMENTS:
2.0 Ft	CRACKED PIPE 120
24.1 Ft	CRACKED PIPE 120
25.2 Ft	OFFSET JOINT 150
34.0 Ft	OFFSET JOINT 150
42.1 Ft	OFFSET JOINT 150
50.7 Ft	OFFSET JOINT 150
63.0 Ft	START SAG IN LINE 130
71.5 Ft	OUT OF SAG IN LINE
75.1 Ft	OFFSET JOINT 150
82.3 Ft	LATERAL LEFT @ 10 O'CLOCK
87.5 Ft	OFFSET JOINT 150
91.7 Ft	OFFSET JOINT 150
96.0 Ft	OFFSET JOINT 150
103.7 Ft	OFFSET JOINT 150
112.7 Ft	OFFSET JOINT 150
131.3 Ft	OFFSET JOINT 150

143.0 Ft	OFFSET JOINT 150
147.5 Ft	OFFSET JOINT 150
153.7 Ft	LATERAL LEFT @ 10 O'CLOCK
168.7 Ft	LATERAL LEFT @ 10 O'CLOCK
172.4 Ft	OFFSET JOINT 150
184.1 Ft	OFFSET JOINT 150
202.0 Ft	LATERAL RIGHT @ 2 O'CLOCK
209.3 Ft	OFFSET JOINT 150
212.9 Ft	OFFSET JOINT 150
216.6 Ft	LATERAL LEFT @ 10 O'CLOCK
220.0 Ft	CRACKED PIPE 120
221.3 Ft	OFFSET JOINT 150
225.3 Ft	OFFSET JOINT 150
259.0 Ft	OFFSET JOINT 150
266.7 Ft	OFFSET JOINT 150
270.2 Ft	START SAG IN LINE 130
275.1 Ft	OFFSET JOINT 150
277.3 Ft	OUT OF SAG IN LINE
287.8 Ft	OFFSET JOINT 150
298.5 Ft	LATERAL LEFT @ 10 O'CLOCK
300.1 Ft	OFFSET JOINT 150
302.1 Ft	CRACKED PIPE 120
305.8 Ft	START SAG IN LINE
312.8 Ft	OFFSET JOINT 150
316.7 Ft	OFFSET JOINT 150 CRACKED PIPE 120
353.0 Ft	OFFSET JOINT 150
361.5 Ft	OFFSET JOINT 150
366.2 Ft	OFFSET JOINT 150
370.5 Ft	OFFSET JOINT 150
373.6 Ft	OFFSET JOINT 150
382.2 Ft	OFFSET JOINT 150

398.3 Ft

OFFSET JOINT 150

402.8 Ft

OFFSET JOINT 150

432.9 Ft

SAG IN LINE
(CAMERA UNDER WATER) 130

442.9 Ft

END OF LINE
LINE POOR
FAIR

AAA PIPELINE INSPECTION
6308 KENNETH AVE.
ORANGEVALE, CA. 95662
916-988-7198

LOG REPORT
04-07-99

CITY:MOUTAIN VIEW
DATE:04-07-99
OPERATOR:JOSE MONTOYA
TAPE#20
TAPE START:2614
MAP PAGE:F-6
SET UP#:MVT20-11

PIPE INFORMATION
UPSTREAM MH#69
DOWNSTREAM MH#53
PIPE TYPE:VCP
PIPE SIZE:12"
STREET:WHISMAN RD.
TV WITH THE FLOW

THANK YOU FOR CHOOSING
AAA PIPELINE INSPECTION

(C)
150x14 offset joints
CRACKS 120x3
SAGS 130x2

FOOTAGE:	FAULT OR COMMENTS:
23.1 Ft	OFFSET JOINT 150
35.4 Ft	OFFSET JOINT 150
39.3 Ft	OFFSET JOINT 150
76.0 Ft	OFFSET JOINT 150
80.0 Ft	OFFSET JOINT 150
125.4 Ft	OFFSET JOINT 150
175.2 Ft	OFFSET JOINT 150
178.9 Ft	OFFSET JOINT 150
241.7 Ft	START SAG IN LINE 130
255.8 Ft	OFFSET JOINT 150
260.1 Ft	OFFSET JOINT 150
270.1 Ft	CRACKED PIPE 120
271.0 Ft	SAG IN LINE (CAMERA UNDER WATER) 130
321.5 Ft	OFFSET JOINT 150
334.5 Ft	OFFSET JOINT 150
341.8 Ft	OFFSET JOINT 150

346.0 Ft

OFFSET JOINT

150

429.1 Ft

CRACKED PIPE

120

436.2 Ft

CRACKED PIPE

120

437.0 Ft

DROP INLET

442.5 Ft

END OF LINE

LINE ~~POOR~~

FAIR

AAA PIPELINE INSPECTION
6308 KENNETH AVE.
ORANGEVALE, CA. 95662
916-988-7198

LOG REPORT
04-12-99

CITY:MOUTAIN VIEW
DATE:04-12-99
OPERATOR:JOSE MONTOYA
TAPE#20
TAPE START:2842
MAP PAGE:F-6
SET UP#:MVT20-12

PIPE INFORMATION
UPSTREAM MH#53
DOWNSTREAM MH#21
PIPE TYPE:VCP
PIPE SIZE:15"
STREET:WHISMAN RD.
TV WITH THE FLOW

THANK YOU FOR CHOOSING
AAA PIPELINE INSPECTION

FOOTAGE:

FAULT OR COMMENTS:

123.9 Ft

LATERAL LEFT @ 10 O'CLOCK
INFILTRATION INTO PIPE

169.4 Ft

CRACKED PIPE

198.8 Ft

LATERAL LEFT @ 10 O'CLOCK
CRACKED PIPE

306.5 Ft

LATERAL LEFT @ 10 O'CLOCK

313.8 Ft

LATERAL LEFT @ 10 O'CLOCK

360.6 Ft

END OF LINE
LINE POOR

Metal Band w/ Diet type

Cracks 2x120
Infiltration 1x180

(B)

AAA PIPELINE INSPECTION
6308 KENNETH AVE.
ORANGEVALE, CA. 95662
916-988-7198

LOG REPORT
04-12-99

(A)

CITY:MOUTAIN VIEW
DATE:04-12-99
OPERATOR:JOSE MONTOYA
TAPE#20
TAPE START:3033
MAP PAGE:F-6
SET UP#:MVT20-13

PIPE INFORMATION
UPSTREAM MH#21
DOWNSTREAM MH#19
PIPE TYPE:VCP
PIPE SIZE:15"
STREET:WHISMAN RD.
TV WITH THE FLOW

THANK YOU FOR CHOOSING
AAA PIPELINE INSPECTION

FOOTAGE:

61.2 Ft

FAULT OR COMMENTS:

END OF LINE
LINE GOOD